

MICROCOPY RESOLUTION TEST CHART
NATIONAL BROKEN TAX TAX TAX TAX



APPRO/ED FOR PUBLIC RELEASE DISTRIBUTION UNLIMITED

PTPD Report No. 83-R-05 AFPEA Report No. 83-P7-132

EDWARD J. KOWALSKI

Mechanical Engineer Design Division HQ AFALD/PTPD

AUTOVON 787-3362 Commercial (513) 257-3362

QUALIFICATION TESTING

CNU-263/E MAYERICK MISSILE CONTAINER

HQ AFALD/PTP
AIR FORCE PACKAGING EVALUATION AGENCY
Wright-Patterson AFB OH 45433

September 1983



100

NOTICE

When government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related government procurement operation, the United States Government thereby incurs no responsibility whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other nerson or corporation, or conveying any rights or permission to manufacture, use, or sell any paterted invention that may in any way be related thereto. This report is not to be used in whole or in part for advertising or wiles purposes.

AFPEA PROJECT NO. 83-P7-132

TITLE: Qualification Testing CNU-263/E Maverick Missile Container

ABSTRACT

The Government of Switzerland is procuring AGM-65B Maverick Missiles from Hughes Aircraft thru the U.S. Government. The Maverick Missile containers CNU-263/E used for transporting/storage of the AGM-65B, will be fabricated by the Government of Switzerland.

The Air Force Packaging Evaluation Agency, WPAFB OH was requested by the Government of Switzerland to furnish services for qualification testing of a production prototype container.

Tests were conducted in accordance with Federal Test Method Standard No. 101, Military Standard-648, and Military Standard-810.

Results of all the tests are acceptable. The production type containers CNU-263/E will give adequate protection to the AGM-65B Maverick Missile during transportation/storage.

Accession For	
NTIS GRA&I	×
DTIC TAB	
Unannoanced	
Justific tion.	
By Distribute b/ Avail	
Dist	1 1
A-/	

EDWARD J. KOWALSKI, Mech Engr Design Division AF Packaging Evaluation Agency

REVIEWED BY

RALPH Chief, Design Division

AF Packaging Evaluation Agency

PUBLICATION DATE:

0 2 SEP 1983

APPROVED BY

JACK E. THOMPSON

Director, Air Force Packaging

Evaluation Agency

TABLE OF CONTENTS

	Page
Abstract	i
Table of Contents	ii
Introduction	1
Background	1
Purpose	1
Test Specimens	1
Test Outline and Test Equipment	1
Test Procedure and Results	1
Test No. 1	1
Test No. 2	1
Test No. 3	2
Test No. 4	2
Test No. 5	2
Test No. 6	2
Test No. 7	2
Test No. 8	3
Test No. 9	3
Test No. 10	3
Test No. 11	3
Test No. 12	3
Test No. 13	4
Test No. 14	4
Test No. 15	4
Conclusion	4
Recommendation	4
Table I. Container Test Plan	6
Table II. Visual Inspection Report	10
Figure 1. CNU-263/E Maverick Missile Container	11
Figure 2. Packaging of Strapping and Restraint Assemblies	11
Figure 3. AGM-65E Inert Maverick Missile, Assembled for Container Testing	11
Figure 4. Pressure/Vacuum Container Leak Test	12

			Page
Figure	5.	Vibration (Repetitive Shock) Test	12
Figure	6.	Vibration (Repetitive Shock) Test with Superimposed-Load	12
Figure	7.	Superimposed-Load Test	13
Figure	8.	Forklift Handling Test	13
Figure	9.	Forklift Handling Test	13
Figure	10.	Forklift Handling Test	14
Figure	11.	Towing Ring Test from End Position	14
Figure	12.	Towing Ring Test From Side Position	14
Γigure	13.	Hoisting/Tie-Down Provisions Test	15
Figure	14.	Cover Handle Pull Test	15
Figure	15.	Rain/Wind Test	15
Figure	16.	Cornerwise-Drop (Rotational) Test, Container End	16
Figure	17.	Edgewise-Drop (Rotational) Test, Container End	16
Figure	18,	Edgewise-Drop (Rotational) Test, Container Side	16
Figure	19.	Pendulum-Impact Test, Container End	17
Figure	20.	Pendulum-Impact Test, Container Side	17
Distrib	outio	on List	36

INTRODUCTION

<u>Background</u>: The Government of Switzerland is procuring AGM-65B Maverick Missiles through the US Government, from Hughes Aircraft, Tucson, Arizona. Missile containers, CNU-263/E used for transporting and storage of the AGM-65E missile will be manufactured by the Government of Switzerland. The Air Force Packaging Evaluation Agency (AFPEA) was requested to furnish services for qualification testing of the prototype container.

<u>Purpose</u>: The purpose of this project was to determine if the prototype container CNU-263/E will protect its contents, the AGM-65B Maverick Missile, during transportation and storage.

Test Specimen: One CNU-263/E Maverick Missile container, serial number CH-001, fabricated from fiberglass materials (resin transfer molded) by Siegfried Peyer AG Switzerland CH-8832 Woolerau was furnished by the Government of Switzerland for testing.

Test Outline and Test Equipment

Tests were conducted in accordance with the AFPEA container test plan, project number 83-P7-132 Amend 1, dated 26 July 1983 (Table I). Test methods and procedures used were as outlined in Federal Test Method Standard No. 101, Military Standard-648, and Military Standard-810. Instrumentation and equipment used are annotated in each test procedure. The container shall limit transmission of shocks to the contents to a maximum of 40Gs resultant force.

Test Procedure and Results

Test No. 1: The container, as received, was visually inpsected. The exterior and interior surfaces, markings, hardware, cushioning, strapping, and container seal were inspected for material and manufacturing imperfections.

Results: Results of the visual inspection are annotated in Table II. Slight damage was noted to the gel-coat on one of the forklift pockets and no provision was noted for a security seal. Figure 1 illustrates overwrap of paper fiberboard and wooden skid removed from the container. Figure 2 illustrates packaging of the strapping assemblies and the restraint assembly as received from the fabricator. Workmanship of the container is rated as excellent.

Test No. 2: An AGM-65/E inert Maverick Missile was mounted in the CNU-263/E container (figure 3). The container T-bolts were torqued to 45 inch pounds and the container was tested for pressure and vacuum leaks. Pressure and vacuum tests were performed at 1.00 psig. The failure criteria for each test was 0.025 psig for a 30-minute period (figure 4).

<u>Results</u>: At the end of the 30-minute pressure/vacuum test period, the results were as follows:

Pneumatic Pressure Test - 0.0162 psig. Vacuum Test - 0.0220 psig

The results of the tests are acceptable.

Test No. 3: Figure 5 illustrate: the container placed on a L.A.B. Corporation, Skaneateles, NY, Vibration Test Machine (LWVH), Type 5000-96B, serial number 56801. The container was placed on, but not fastened to the platform. Restraining blocks were attached to the platform to prevent the container from moving off the platform. A clearance of approximately 1/2 inch in all directions was used on the restraint blocks to allow free movement of the container auring the 1/2 hour test period. With the container in position, the platform was vibrated until the container raised from the platform (1/16 inch feeler clearance between bottom of container and platform) for a maximum platform acceleration of 1G. The test was instrumented with a tri-axial accelerometer and was conducted at the ambient temperature.

Results: A maximum of 3Gs was obtained during the 1/2 hour test period of the repetitive shock test. The results of the test are acceptable.

Test No. 4: This test was conducted with the same procedure as test No. 3, except a superimposed load of two additional containers were placed on top of the original test container. Figure 6 illustrates the strapping of the three containers also, the tie-down of the containers to the platform.

Results: A maximum of 3Gs was obtained during the 1/2 hour test period of the superimposed load repetitive shock test. The results of the test are acceptable.

Test No. 5: Figure 7 illustrates the container as placed on the platen of a high capacity (50,000 pound) Compression Tester, Testing Machine, Inc., Amityville, NY model No. 17-24-2. A 2199 pound compression load was applied to the test container for a period of one hour. The test was observed for deflection, permanent deformation, and structural failure of the container cover and base assembly. The test was conducted at the ambient temperature.

hesults: Inspection during and after the test did not reveal any damage to the container. Results of the test are acceptable.

lost No. 6: Figures 3, 9, and 10 illustrate the mechanical handling tests conducted with a 4,000 pound capacity hard rubber tired electric operated forklift truck. The tests included a one high, two high, and a three high container transport. The container(s) were lifted clear and transported on the forklift truck forks across a hard pavement for a distance of 100 feet. Parallel pairs of 1x3 inch lumber were laid flatwise on the pavement across the path of the forklift truck. The container(s) were carefully observed for any damage during the travel and stopping operations. Figures 11 and 12 illustrates the towing test. A strap was attached to the towing rings and the container was complete first from the end position and then from the side position allows a hard pavement for a distance of 100 feet. The container was observed during travel for any damage that may have occurred.

Results: From inspection, no visual damage was noted to the container during the mechanical handling or the towing tests. Results of the tests are a contable.

Test No. 7: Figure 13 illustrates the hoisting/tie-down provisions test. A 3665 pound load was placed on the test container. The test container was raised off the floor and held in that position for one hour. A leak test was performed at the end of the hoisting/tie-down test.

Results: Inspection during and after the hoisting/tie-down test did not reveal any damage to the container. At the end of the 30 minute pressure/vacuum test period, the results of the leak test were as follows:

Pneumatic Pressure Test - 0.000 psig. Vacuum Test ----- 0.013 psig.

The results of the tests are acceptable.

Test No. 8: The conductive path test was performed by checking the DC OHM resistance from each terminating and breaking point from the missile skin to the external ground.

<u>Results</u>: The conductive path test measured 0.0068 DC OHM resistance. Results of the test are acceptable.

Test No. 9: Figure 14 illustrates the cover handle pull test. A calibrated scale was used to measure the 300 pound pull applied to the handles. The load was applied from several different angles to compensate for various methods of lifting the cover assembly.

<u>Results</u>: Visual inspection revealed no physical damage to the handles or cover of the test container. The results of the test are acceptable,

Test No. 10: An internal pressure of 1.50 psig was applied to the container for a test period of 15 minutes. The test container was tested for structural failure and permanent deformation of the lower and upper shells, and also for any structural failure around the handles and hoisting/tie-down rings.

<u>Results</u>: Visual inspection revealed no physical damage to the fiberglass material. The results of the test are acceptable.

Test No. 11: Figure 15 illustrates the test container in a test position in the rain/wind chamber. The test was conducted at simulated rainfall at a rate of 2 and 5 inches per hour and a horizontal wind velocity of 40 miles per hour. The test container was placed in the chamber at a 30 degree angle for a test period of 30 minutes. At the end of the 30 minute test period, the container was placed at a 330 degree angle for an additional test period of 30 minutes. At the end of the one hour test period, the container was removed from the chamber rotated 180 degrees, placed in the chamber and the test continued for an additional one hour period using the same test procedure. At the conclusion of the rain/wind exposure the test container was removed from the chamber, the moisture was removed from the exterior surface, and the container opened for inspection.

Results: Visual inspection revealed no water entry to the interior of the test container. The results of the test are acceptable,

Test No. 12: Figure 16 illustrates the cornerwise-drop (rotational) test. The height of drop on each of the four corners was at 20 inches. The drop height of 20 inches was based on the length dimension and not the weight of the test specimen. The test specimen was instrumented for the drop tests. One corner of the container was supported on a 12-inch block height. The opposite corner, same end, was supported on a 6-inch block height. The unsupported end

of the container was then raised so that the lower corner (6-inch support side) was at 20 inches from the floor. The electric quick release hook (L.A.B. Corporation, Skaneateles, NY, serial No. 5090208, 6,000 pound capacity) was energized and the test container allowed to fall on a concrete surface.

Results: Visual inspection of the test container revealed no damage. A maximum of 14.4Gs was obtained during the tests. The results of the tests are acceptable.

Test No. 13: Figures 17 and 18 illustrate the edgewise-drop (rotational) test. The height of drop on each of the four edges was at 20 inches. The drop height of 20 inches was based on the length dimension and not the weight of the test specimen. The test specimen was instrumented for the drop tests. The edge of the container was supported on a 6-inch block height. The unsupported edge was then raised so that the height was 20 inches from the floor. The electric quick release hook (L.A.B. Corporation, Skaneateles, NY, serial No. 5090208, e.000 pound capacity) was energized and the test container allowed to fall on a concrete surface.

Results: Visual inspection of the test container revealed no damage. A maximum of 16,40s was obtained during the tests. The results of the tests are acceptable.

lest No. 14: Figures 19 and 10 illustrate the pendulum-impact test. The instrumented test container was placed on a platform and the end/side to be impacted was placed beyond the front end of the platform so that it could impact against a bumper. The platform was pulled back to a vertical drop height of 9 inches and released to swing freely so that the end/side of the container impacted against the bumper. A drop height of 9 inches results in a velocity of 7 feet over second at impact.

Results: Visual inspection of the test container revealed no damage. A maximum of 13.73s was obtained during the tests. The results of the tests are acceptable.

Test No. 15: Pressure and vacuum tests were performed on the test container. Pressure and vacuum tests were performed at 1.00 psig. The failure criteria as a cash test was - 0.075 psig for a 50-minute period (Figure 4).

Results: At the end of the 30-minute pressure/vacuum test period, the results were as follows:

Preumatic Pressure Test - 0.000 psig. Vacuum Test ----- 0.022 psig.

The results of the tests are acceptable,

constants from the results obtained, the container CNU-263/E submitted by strigffried Peyer AG Switzerland will give adequate protection to the AGM-68E Miverick Missile during shipment/storage. The resultant maximum 16,4Gs was below the limit of 40Gs. The lower and upper flanges and the gasket are a dior improvement over the original design of the container. Craftsmanship as considered excellent.

Recommendations: The following are recommendations for use in the assembly/disassembly of the CNU-203; Maverick Missile containers during the storage of AGM-65E Maverick Missiles:

- 1. <u>CAUTION</u>, when removing cover assembly, Dwg A-35204-2, S. Peyer LTD., CH, <u>DO NOT</u> place closure flange of cover assembly on floor. Turn cover assembly 180 degrees and place top of cover assembly on floor to prevent damage to flange surface, and also prevent accumulation of debris on the silicone compound (Figure 2).
- 2. <u>CAUTION</u>, prior to assembly of container, wipe cover and base assembly flanges with lint-free material to remove any contaminants that may have accumulated.
- 3. <u>CAUTION</u>, examine vulcanized joint of gasket, Dwg A-35210-2, S. Peyer LTD CH, joint shall have smooth surfaces for good sealing properties.
- 4. CAUTION, apply coating of G.E. silicone dielectric compound MIL-S-8660, GE Part No. G-624, NSN 6850-00-880-7616, prior to assembly of container.
- 5. <u>CAUTION</u>, torque T-bolts, Dwg 35218-2, S. Peyer LTD. CH, to 45 inch pounds. <u>Container WILL NOT</u> pressure/vacuum seal, if correct torque is not maintained.

[AIR FO	RCE PACKAGING	EVALUAT	ION AGI	ENCY	AFPEA PROJ	ECT NUMBEH
	,,,,,,	(Container T				83-P7-13	BE AMEND 1
•		(L X W X D)(INCHES)	1	T (LBS)	CUBE (CU. FT.)	QUANTITY	DATE
IN.	NTERIOR	EXTERIOR:	GROSS	ITEM: 35의	54	1	26 Jul 🕾
ITEM NA		orick Missile	1	MANUFAC SWIS		.	
CONTAI	NEH NAME				CONTAINER	COST	
21;	(1- e 1 t)				s N/A		
PACK DE	ESCRIPTION				J	·· · · · - ·	
Fi	bergiass c	construction					
CONDIT	IONING						
âs.	noted in	test plan					
TEST NO.	REF STO AND TEST N PROCEDU	IETHOD OR TEST T	ITLE AND PAR	RAMETERS		ITAINER NTATION	INSTRU- MENTATION

In use of the activity of the total bundle practical, a dummy load shall be subjects to the amplication of the electrical weight, hape, center of mavilla, The order to be a series of th the pattern centures to the feet additional one are nequired for etacking/ display contiguration tectors. The closible ontainer(a) shall be assembled, larger, couled to feet display to all tests, except where specific modification seemal) to obtain the total conditional display and configured and the call part of the sequence. The tests of the first contains such the approved test plan as shown below. The lines writering the second of the STD-CD, can death 3.2.6 of General approximately. The transfer of the sign of the second of the se places or a incation convergering to the item conten-of-gravity with ales consists of the form of the line of the control of the forklift posket of the potter container.

COMMENTS

COMALSE. Men Engr. AFFIA AFALD 4

APPROVE BY

I RALPH ZYNDA.

an Division, AFPEA -

1 1 1

	AIR FOR	-	KAGING Container T	EVALUATI est Plan)	ON AGI	ENCY		83-P7-13	2 AMEND 1
	NTAINER SIZE (NCHES) ERIOR:	WEIGHT GROSS:	(LBS) ITEM:	CUB	E (CU. FT.)	QUANTITY	DATE
EM NA					MANUFAC	TURER		<u> </u>	26 Jul 83
	M-65B Mave	rick Miss	116		<u> </u>		CONTAINES		
	NER NAME IU-263/E					1	CONTAINER	COSI	
	ESCRIPTION								
FI	berglass co	onstructi	on			<u>. </u>			
TEST NO.	REF STD AND TEST ME PROCEDUR	SPEC THOD OR IE NO's	TEST T	ITLE AND PAR	AMETERS			TAINER	INSTRU- MENTATION
1.			Visual in of test.	nspection	before s	tart			
2.	Fed-Std- Method	1	Relief varietic. Pressure Vacuum Presilure	Container alve repla tight val Test - l. ressure - Criteria T n 30 minut	ced with ve. Pne O psig 1.0 psig est - O.	·u-	As requ	ired	. ⊰r ⊣anometer
3.	Mil-Std- Sec. 5. Fed-Std- Sec. 50	2.2 and 101	Test. 3	n (Repetit to 5 Hz o less for n	r 1G whi	ch-			Tri-axial Accelerome
4.	Mil-Std- Sec. 5.		Test wit	n (Repetit h Superimp untested c	osed Loa	d.	equal to like con high, ri	nposed load to three ontainers igidly ed to excit	Accelerome
5.	Fed-Std- Method Mil-Std- Sec. 5.	5016.1 648	Superimposed-Load Test (Stack-ability with dunnage). Load on bottom container shall be limited to three loaded containers for a safety factor of 2. Test for 1 hr.			On a fl floor	lat rigid	Yes	
6.	Fed-Std- Method Sec. 6	i	Mechanical Handling Test. Sec. 6.2 - Forklift Handling Test. Lift container(s) off ground with tines, then carry			wide the	gh and one nen repeat, gh and one nen repeat,	N/A	
OMME	NTS								.
	ED BY ARD J. KOWA	ISVI MA	h Fnan A	FDFA	APPROVED DAI DH		Chief	Design Div	ision, AFPEA

		Astr .				
AIR FORCE PAC	KAGING Container	· · · · · · · · · · · · · · · · ·	AGENCY		!	ECT NUMBER
CONTAINER SIZE (L X W X D)(I INTERIOR EX	NCHES! EHIOR	WEIGHT (LBS)		E (CU FT.)	QUANTITY	DATE
TENINAME A MEDRA No. 11 - MIS. T. CATAINER NAME	?. 	MAN	UFACTUHER	CCNTAINER	COST	. ' · ·
ACN DESCRIPTION				•• =		
riturglass construction			-		· · · ·	· · · · · ·
TEST REFISTO SPECTAND TEST METHOD OR PROCEDURE NOS	1F S 1	TITLE AND PARAMETE	ERS i		ITAINER NTATION	-, INSTRU MENTATION
	the control of the co	to the Critical of the Critical state of the	a solution of the solution of	three '	t to and a total out	
	1 dewis Hidewis	tife 13 sect and a.	ng Present	, 11 *3 %		•
**************************************	Tent. Paded of weight. Page to the control of the c	Sentained shall to b times gross Lift container ollhour. Legs hall be greater harizontal. Leak	be s loaded mand let of the than 30 ⁰ Perform			
	(311.35°) •••	ive Jath Test. ive path test no in pooper movings coinciting and br	unc⊬ frem			Chrim etch

	AIR FOR			EVALUAT	ION AG	ENC	•	AFPEA PROJEC	
			Container					83-P7-132	
	NTAINER SIZE (NTERIOR: 1		NCHES) ERIOR:	WEIGHT GROSS.	(LBS)	CUB	E (CU. FT.)	QUANTITY	DATE
									26 Jul 83
TEM NA	ime -65B Maverio	de Minai			MANUFA	CTURE	₹		
	NER NAME	.K M1221	е — —		<u> </u>		CONTAINER	COST	
•	-263/E						CONTRINEN	COST	
	ESCRIPTION								
Fibe	erglass cons	struction	1						
ONDIT	IONING								
TEST NO.	REF STD S AND TEST ME PROCEDUR	THOD OR	TEST	TITLE AND PAR	AMETERS		1	TAINER NTATION	INSTRU- MENTATION
8. (CO1	IT'D)			rom the mis		in to		;	
9.	! ! 		Pull in	andle Pull every dire loads are	ction t	hat			N/A
10.	Mil-Std-6 Sec 5.6.		Pressure	e Test 1.5	psig				Water Manometer
11.	Mil-Std-8 Method 8 Procedu	506.1,	test dur	Rain with Wind Source. Total As required test duration of not less than 2 hours.				uired	N/A
12.	Fed-Std-1 Method 5			ise-Drop (R om 20" heig		al)		op on each (total 4	Tri-axial Acceleromet
13.	Fed-Std-1 Method 5		Edgwise- from 20"	Drop (Rota height.	tional)	Test		op on each total 4 dro _l	Tri-axial os) Accelerom
14.	Fed-Std-1 Method 5		Pendulum from 9"	n-Impact Te height.	st (7 f	t/sec)	side &	pact to eacl each end 4 impacts)	h N/A
15.				test #2 Pn ter test #1		Leak			
1									
OMME	NTS:					i			
	ED BY:		·		APPROVE				

TABLE 11

Visual Inspection
CNU-263/E Centainer - AGM-65B Maverick Missile

Roquinement	. Accept	Reject '	Remarks
ueight 264 pounds	, x		
Base Jection/Cover Section		in a record of the control of the co	
Forklift Pockets	x 1		Gel-coat slight damage. side of pocket
Stacking Interface	X		
Hoisting/Tie-Down Provisions	į X		
Lesicant Port	X :		** - * - * · · · · · · · · · · · · · · ·
Fumidity Indicator	x		
Pressure Equalizing Valve	х	· · · · · · · · · · · · · · · · · · ·	
Electrical Grounding Connector	х		
Records Receptable	X		
Security Seal			No security sea
Weldments	X		
Identification/Markings	λ 1	1	
human Performance	X		
Clasure Hardware	х		
entriner Seal	X		
Sworioning	×		
Strapping	X		
formulanship	x		Excellent




Figure 1. CNU-263/E Maverick Missile Container, Serial No. CH-001 fabricated by S. Peyer LTD. CH.




Figure 2. Figure illustrates packaging of strapping and restraint assemblies.




Figure 3. AGM-65E inert Maverick Missile assembled for container testing.



Figure 4. Pressure/vacuum container leak test.




Figure 5. Vibration (repetitive shock) test.




Figure 6. Vibration (repetitive shock) test with superimposed load.




Figure 7. Superimposed-Load test.



Figure 8. Forklift handling test.




Figure 9. Forklift handling test.




Figure 10. Forklift handling test.



Figure 11. Towing ring test from end position.




Figure 12. Towing ring test from side position.




Figure 13. Hoisting/tie-down provisions test.




Figure 14. Cover handle pull test.




Figure 15. Rain/wind test.




Figure 16. (ornerwise-dref (rotational) to to container end.



Figure 17. Edgewise-drop (notational) test, container end.



Figure 18. Edgewise-drop (rotational) test. container side.



Figure 19. Pendulum-impact test, container end.




Figure 22. Fendulum-impact test, container offe.

DISTRIBUTION LIST

	Copies
AFALD/PTP Library NPAFB OH 45433	20
AFALD/PT NPAFB OH 45433	1
AFALD/PTPP WPAFB OH 45433	1
HQ AFLC/DST WPAFB OH 45433	1
ASD/AWL WPAFB OH 45433	1
ASD/TAAF-SLO WPAFB OH 45433	5
ASD/TAME WPAFB OH 45433	2
ILC/OOEN WPAFB OH 45433	1
HQ USAF/LETT Wash DC 20330	1
00-ALC/DSP Hill AFB UT 84406	1
OC-ALC/DSP Tinker AFB OK 73145	1
SA-ALC/DSP Kelly AFB TX 78241	1
SM-ALC/DSP McClellan AFB CA 95652	7
WR-ALC/DSP Robins AFB GA 31098	1
DTIC/TSR Cameron Station	12
Alexandria VA 22314	
DLSIE, USA Logistics Mgmt Ctr (DRXHC-D) Ft Lee VA 23801	1
DARCOM (SDSTO-T) Tobyhanna PA 18466	1

DISTRIBUTION LIST

	Copies
US Army Natick Labs (DRDNA-EPS) Natick MA 01760	1
NAVSUPSYSCOM (SUP-0321A) Wash DC 20376	5
ADTC/YXC Eglin AFB FL 32542	1
ASO/TEP-A 4030 700 Robbins Ave Philadelphia PA 19111	١
US Army Armament Research & Development Command (DRDAR-TST-S) Dover NJ 07081	1
GSA, Ofc of Engrg. Mgmt. Packaging Division Wash DC 20406	1
HQ DLA-OWO Cameron Station Alexandria VA 22314	١